PLUS Search Results for S/N 10786197, Searched January 03, 2006

The Patent Linguistics Utility System (PLUS) is a USPTO automated search system for U.S. Patents from 1971 to the present. PLUS is a query-by-example search system which produces a list of patents that are most closely related linguistically to the application searched. This search was prepared by the staff of the Scientific and Technical Information Center, SIRA.

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	79	(ANALYSIS with MEASUREMENT with SERVICES)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 07:29
L2	31	(Gregory with Morton) (Brent with Shumaker) (Hashem with Hashemian)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 07:35
L3	103	1 2	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 07:35
L4	2	3 and (cross with (calibration calibrating calibrate calibrated) with (plant industry industrial factory))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 07:39
L5	8	3 and ((calibration calibrating calibrate calibrated) with (plant industry industrial factory))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 07:42
L6	7	3 and (cross with (calibration calibrating calibrate calibrated))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 07:41
L7	2	3 and (cross with (calibration calibrating calibrate calibrated)) and ((remove removing removal) with (deviate deviating deviation))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 07:42
L8	2	3 and ((calibration calibrating calibrate calibrated) with (plant industry industrial factory)) and ((remove removing removal) with (deviate deviating deviation))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 07:43
L9	2	3 and (cross with (calibration calibrating calibrate calibrated) with (plant industry industrial factory)) and ((remove removing removal) with (deviate deviating deviation))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 07:43
L10	2	(cross with (calibration calibrating calibrate calibrated) with (plant industry industrial factory)) and ((remove removing removal) with (deviate deviating deviation))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 07:44

L11	22	((calibration calibrating calibrate calibrated) with (plant industry industrial factory)) and ((remove removing removal) with (deviate deviating deviation))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 07:50
L12	3	((calibration calibrating calibrate calibrated) with (plant industry industrial factory)) and ((remove removing removal) with (deviate deviating deviation) with data)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 07:56
L13	140	((calibration calibrating calibrate calibrated)) and ((remove removing removal) with (deviate deviating deviation) with data)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 07:51
L14	38	((calibration calibrating calibrate calibrated)) and ((remove removing removal) near (deviate deviating deviation))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 07:51
L15	311	((calibration calibrating calibrate calibrated) with (plant industry industrial factory)) and ((deviate deviating deviation) with data)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 08:02
L16	12	((calibration calibrating calibrate calibrated) with (plant industry industrial factory)) and ((deviate deviating deviation) with data) and ((resistance with temperature with device) rtd)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 08:04
L17	2	((calibration calibrating calibrate calibrated) with (plant industry industrial factory)) and ((deviate deviating deviation) with data) and (recalibrate recalibrating recalibration recalibrated) and ((resistance with temperature with device) rtd)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 08:06
L18	69	((calibration calibrating calibrate calibrated) with (plant industry industrial factory)) and ((deviate deviating deviation) with data) and (recalibrate recalibrating recalibration recalibrated)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 08:08
L19	412	((calibration calibrating calibrate calibrated)) and ((deviate deviating deviation) with data) and (recalibrate recalibrating recalibration recalibrated)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 08:09

L20	201	(plant industry industrial factory) and ((calibration calibrating calibrate calibrated)) and ((deviate deviating deviation) with data) and (recalibrate recalibrating recalibration recalibrated)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 08:06
L21	8	(plant industry industrial factory) and ((calibration calibrating calibrate calibrated)) and ((deviate deviating deviation) with data) and (recalibrate recalibrating recalibration recalibrated) and ((resistance with temperature with device) rtd)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 08:06
L22	2	((calibration calibrating calibrate calibrated) with (plant industry industrial factory)) and ((remove removing removal) with (deviate deviating deviation) with data) and (recalibrate recalibrating recalibration recalibrated)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 08:08
L23	3	((calibration calibrating calibrate calibrated) with (plant industry industrial factory)) and ((remove removing removal) with (deviate deviating deviation) with data)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 08:08
L24	19	((calibration calibrating calibrate calibrated)) and ((removal removing remove) with (deviate deviating deviation) with data) and (recalibrate recalibrating recalibration recalibrated)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 08:19
L25	13	(plant factory industry industrial) and ((calibration calibrating calibrate calibrated)) and ((filter filtering removal removing remove) with (deviate deviating deviation) with data) and (recalibrate recalibrating recalibration recalibrated)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 08:24
L26	36	(plant factory industry industrial) and ((calibration calibrating calibrate calibrated)) and ((filter filtering removal removing remove) with (deviate deviating deviation)) and (recalibrate recalibrating recalibration recalibrated)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 08:30
L27	23	26 not(25)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 08:24

L28	15011	((filter filtering removal removing remove) with (deviate deviating deviation deviated))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 11:33
L29	1049	((filter filtering removal removing remove) near (deviate deviating deviation deviated))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 08:37
L30	1600	(calibrate calibrating calibrated calibration) and ((filter filtering removal removing remove) with (deviate deviating deviation deviated))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 08:36
L31	112	(calibrate calibrating calibrated calibration) and ((filter filtering removal removing remove) with (deviate deviating deviation deviated)) and (recalibrate recalibrating recalibrated recalibration)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 08:36
L32	36	(plant factory industry industrial) and (calibrate calibrating calibrated calibration) and ((filter filtering removal removing remove) with (deviate deviating deviation deviated)) and (recalibrate recalibrating recalibrated recalibration)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 08:39
L33	2	(plant factory industry industrial) and ((calibrate calibrating calibrated calibration) same ((filter filtering removal removing remove) with (deviate deviating deviation deviated)) same (recalibrate recalibrating recalibrated recalibration))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 08:36
L34	2	(calibrate calibrating calibrated calibration) same ((filter filtering removal removing remove) with (deviate deviating deviation deviated)) same (recalibrate recalibrating recalibrated recalibration)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 08:36
L35	243	(calibrate calibrating calibrated calibration) same ((filter filtering removal removing remove) with (deviate deviating deviation deviated))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 08:36

L36	443	((removal removing remove) near (deviate deviating deviation deviated))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 08:37
L37	48	(plant factory industry industrial) and (calibrate calibrating calibrated calibration) and ((separate separating separation filter filtering removal removing remove) with (deviate deviating deviation deviated)) and (recalibrate recalibrating recalibrated recalibration)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 08:40
L38	12	37 not(32)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 08:39
L39	4	(plant factory industry industrial) and (calibrate calibrating calibrated calibration) and ((separate separating separation filter filtering removal removing remove) with (deviate deviating deviation deviated)) and (recalibrate recalibrating recalibrated recalibration) and (rtd (resistance with temperature))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 08:43
L40	4	(plant factory industry industrial) and ((separate separating separation filter filtering removal removing remove) with (deviate deviating deviation deviated)) and (recalibrate recalibrating recalibrated recalibration) and (rtd (resistance with temperature))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 08:43
L41	146	(plant factory industry industrial) and (calibrate calibrating calibrated calibration) and ((separate separating separation filter filtering removal removing remove) with (deviate deviating deviation deviated)) and (rtd (resistance with temperature))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 09:28
L42	5	(plant factory industry industrial) and (calibrate calibrating calibrated calibration) and ((separate separating separation filter filtering removal removing remove) near (deviate deviating deviation deviated)) and (rtd (resistance with temperature))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 08:44

		- management and the second se				
L43	2	(plant factory industry industrial) and ((calibrate calibrating calibrated calibration) same ((separate separating separation filter filtering removal removing remove) with (deviate deviating deviation deviated)) same (rtd (resistance with temperature)))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 08:55
L44	6	(plant factory industry industrial) and ((calibrate calibrating calibrated calibration) same ((separate separating separation filter filtering removal removing remove) with (deviate deviating deviation deviated))) and (rtd (resistance with temperature))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 08:57
L47	1	(plant factory industry industrial) and (calibrate calibrating calibrated calibration) and ((separate separating separation filter filtering removal removing remove) with (deviate deviating deviation deviated)) and (rtd (resistance with temperature)) and (cet (core with exist with thermocouple))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 09:20
L48	93	(plant factory industry industrial) and (calibrate calibrating calibrated calibration) and ((separate separating separation filter filtering removal removing remove) with (deviate deviating deviation deviated)) and (rtd (resistance with temperature)) and (cet (thermocouple))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 09:23
L49	84	(plant factory industry industrial) and (calibrate calibrating calibrated calibration) and ((separating separation filtering removal removing) with (deviate deviating deviation deviated)) and (rtd (resistance with temperature)) and (cet (thermocouple))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 09:23
L50	896	(plant factory industry industrial) and (calibrate calibrating calibrated calibration) and ((separate separating separation filter filtering removal removing remove) with (deviate deviating deviation deviated))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 09:29

L51	9	(plant factory industry industrial) same (calibrate calibrating calibrated calibration) same ((separate separating separation filter filtering removal removing remove) with (deviate deviating deviation deviated))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 09:29
L52	21512	((filter filtering removal removing remove separate separating separation) with (deviate deviating deviation deviated))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 11:34
L53	1984	((filter filtering removal removing remove separate separating separation) with (deviate deviating deviation deviated)) and (calibrate calibrating calibration)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 11:35
L54	792	((filter filtering removal removing remove separate separating separation) with (deviate deviating deviation deviated)) and (calibrate calibrating calibration) and (plant factory industry industrial)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 11:37
L55	42	((filter filtering removal removing remove separate separating separation) with (deviate deviating deviation deviated)) and (calibrate calibrating calibration) and (plant factory industry industrial) and (recalibrate recalibrating recalibration)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 12:07
L56	9	((filter filtering removal removing remove separate separating separation) near (deviate deviating deviation deviated)) and (calibrate calibrating calibration) and (plant factory industry industrial) and (recalibrate recalibrating recalibration)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 12:00
L57	16	((removal removing remove) with (deviate deviating deviation deviated)) and (calibrate calibrating calibration) and (plant factory industry industrial) and (recalibrate recalibrating recalibration)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 12:07